PHOTOGRAPHIC RECORD OF WORKS PROGRESS
OPERATIONS LAVATORY REFURBISHMENT

At:
Enfield Bus Garage
Southbury Road
Enfield
Middlesex
EN2 4HX

For:
Arriva London North Limited
203 Isledon Road
London
N7 7JR

Prepared by:
Brasier Freeth LLP
3rd Floor
Roxburghe House
20 Great Castle Street
London
W1G 0HY

Issued: 27/02/2018 **Revision: 0**

CONTENTS

PHOTOGRAPHS BEFORE WORKS	3
PHOTOGRAPHS DURING WORKS	10
PHOTOGRAPHS AFTER COMPLETION OF WORKS	25

PHOTOGRAPHS BEFORE WORKS

PHOTO 1.1
Shower Cubicle to male WC



PHOTO 1.2
Bench in male WC



PHOTO 1.3
Male WC



PHOTO 1.4
Toilet cubciles to male WC



PHOTO 1.5
Redundant toilet cubicle to male WC



PHOTO 1.6
Male WC



PHOTO 1.7
Wash basin troughs to male WC



PHOTO 1.8
Cleaners store room



PHOTO 1.9
Wash hand basins to female WC.



PHOTO 1.10
Toilet cubicles to female WC.



PHOTO 1.11
WC cubcile to female WC.



PHOTO 1.12
Shower cubicle to female WC



PHOTO 1.13
Electrical distribution board in cleaners store room serving WC areas.



PHOTO 1.14
Corridor to male WC leading to shower cubicles.




PHOTO 1.15
Service riser to WC's between male and female toilet cubicles.



PHOTO 1.16
Mechanical extraction to service riser. Note: mechanical extraction not working.




PHOTO 1.17
Internal inspection chamber cover.



PHOTO 1.18
Entrance doors into male and female lavatories.



PHOTOGRAPHS DURING WORKS

PHOTO 1.19
Strip out of wall and floor coverings to female shower cubicle.



PHOTO 1.20
Alterations to the existing mechanical extraction / ventilation system.



PHOTO 1.21
Removal of suspended MF ceiling exposing void and services above.



PHOTO 1.22
New electrical services chased into walls.



PHOTO 1.23
Removal of WC's in male toilet with only drainage routes left.



PHOTO 1.24
Male WC following strip out.



PHOTO 1.25
Male WC following strip out. Note: Wall where urinals and raised plinth used to be.



PHOTO 1.26
Strip out to male WC. Note: location where wash basin troughs used to be.



PHOTO 1.27
New latex levelling floor screed to male shower cubicles.




PHOTO 1.28
Pipework services located above suspended MF ceiling to male shower cubicles.




PHOTO 1.29
Herras fencing to entrance to site area with health and safety signage in place and debris netting fitted.




PHOTO 1.30
New inspection chamber frame installed.



PHOTO 1.31
Service riser with cisterns removed.



PHOTO 1.32
Health and safety notice board to herras fencing.



PHOTO 1.33
New PVC wall cladding.



PHOTO 1.34
New PVC wall cladding installed.



PHOTO 1.35
Wall cladding installed to shower cubicle




PHOTO 1.36
Male cladding to male WC



PHOTO 1.37
Squatting WC pan being installed on raised step.



PHOTO 1.38
New ducting installed to male WC.



PHOTO 1.39
PVC wall cladding to male shower cubicle.



PHOTO 1.40
Female WC.



PHOTO 1.41
Male WC.



PHOTO 1.42
Male WC.



PHOTO 1.43
WC's being installed to female WC.




PHOTO 1.44
Non-slip floor tiles being installed to female shower cubicle.



PHOTO 1.45
Squatting WC pan to male WC.



PHOTO 1.46
Urinals and high level cistern being installed to male WC.



PHOTO 1.47
New shower applicances.



PHOTO 1.48
New hand driers and radiator installed to male WC.



PHOTO 1.49
WC cubicles installed to female WC.



PHOTO 1.50
Wash basin trough being installed to female WC.




PHOTO 1.51
Wash basin troughs and vanity unit installed to male WC.




PHOTO 1.52
Existing doors being refurbished and redecorated.



PHOTO 1.53
New sealed manhold cover installed.




PHOTO 1.54
New suspended ceiling grid with lay in tiles installed. Note: new lighting.



PHOTO 1.55
New cisterns, drainage and copper pipework installed to service riser.



PHOTO 1.56
New distribution board being installed.



PHOTOGRAPHS AFTER COMPLETION OF WORKS

PHOTO 1.57
Male WC.



PHOTO 1.58
Male WC.



PHOTO 1.59
Male WC cubicles.



PHOTO 1.60
Urinals to male WC.



PHOTO 1.61
Wash basin troughs to male WC.



PHOTO 1.62
Squatting WC pan to male WC.



PHOTO 1.63
WC cubicle to male WC.



PHOTO 1.64
Female WC.



PHOTO 1.65
WC cubicles to female WC.



PHOTO 1.66
New distribution board installed to cleaners store room.



PHOTO 1.67
Corridor leading to males shower cubicles.




PHOTO 1.68
Entrance doors to male and female lavatories.




PHOTO 1.69
Service riser.



PHOTO 1.70
Alterations to existing mechanical extract and ventilation system.

